


S1000-K1 Wiring Diagram
 (European General Export Model)



LEFT HANDLEBAR SWITCH CONNECTIONS

Switch	Color	Wiring	Ground Point
Left Turn Signal	Blue	SW1-1	SW1-2
Right Turn Signal	Red	SW1-3	SW1-4
Headlight	Black	SW1-5	SW1-6
Horn	Yellow	SW1-7	SW1-8
Ignition	Black	SW1-9	SW1-10
Accessory	Green	SW1-11	SW1-12

IGNITION SWITCH CONNECTIONS

Terminal	Color	Wiring	Ground Point
1	Black	IGN-1	IGN-2
2	Red	IGN-3	IGN-4
3	Blue	IGN-5	IGN-6
4	Green	IGN-7	IGN-8
5	Yellow	IGN-9	IGN-10

RIGHT HANDLEBAR SWITCH CONNECTIONS

Switch	Color	Wiring	Ground Point
Right Turn Signal	Red	SW2-1	SW2-2
Left Turn Signal	Blue	SW2-3	SW2-4
Headlight	Black	SW2-5	SW2-6
Horn	Yellow	SW2-7	SW2-8
Ignition	Black	SW2-9	SW2-10
Accessory	Green	SW2-11	SW2-12

Color Code

Color	Wiring	Ground Point
Black	IGN-1	IGN-2
Red	IGN-3	IGN-4
Blue	IGN-5	IGN-6
Green	IGN-7	IGN-8
Yellow	IGN-9	IGN-10
Black	IGN-11	IGN-12
Red	IGN-13	IGN-14
Blue	IGN-15	IGN-16
Green	IGN-17	IGN-18
Yellow	IGN-19	IGN-20
Black	IGN-21	IGN-22
Red	IGN-23	IGN-24
Blue	IGN-25	IGN-26
Green	IGN-27	IGN-28
Yellow	IGN-29	IGN-30